

YOSHIHIKO WATANABE, et al.

Examiner: P. Huntsinger

Appl. No.: 09/840,157

Group Art Unit: 2625

Filed: April 24, 2001

5312

For: APPLICATION CHARGING SYSTEM,

INFORMATION PROCESSING APPARATUS, AND CONTROL

METHOD THEREFOR AND MEMORY MEDIUM STORING

PROGRAM THEREFOR

U.S. Patent No.: 7,154,616 B2

Issued: December 26, 2006

November 21, 2007

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

> 11/27/2007 SZEWDIE1 00000109 7154616 01 FC:1811 100.00 OP

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Edward A. Kmett Attorney for Patentees Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS_WS 1582749v1

Form #33 - 2 -

CERTIFICATE OF CORRECTION

PATENT NO. : 7,154,616 B2

DATED : December 26, 2006

INVENTOR(S) : Watanabe, et al.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS:

SHEET 10:

FIG. 11, in block 33, "PRINT DRIVVER" should read -- PRINT DRIVER --.

COLUMN 2:

Line 62, "ve" should read -- be --.

COLUMN 5:

Line 8, "shape" should read -- shape, --;

Line 9, "etc." should read -- etc., --;

Line 28, "applicational," should read -- application --;

Line 40, "standalone" should read -- stand-alone --; and

Line 53, "in" should read -- in the --.

COLUMN 7:

Line 7, "sheets" should read -- sheets, --; and

Line 10, "erared" should read -- erased --.

COLUMN 8:

Line 24, "apparatus" should read -- apparatus, --; and

Line 44, "MFP 3" should read -- MFP 3, --.

COLUMN 9:

Line 26, "where by" should read -- whereby --; and

Line 51, "listg" should read -- list --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 29 2007

PATENT NO. 7,154,616 B2



CERTIFICATE OF CORRECTION

PATENT NO. : 7,154,616 B2

DATED: December 26, 2006

INVENTOR(S) : Watanabe, et al.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 48, "process" should read -- processes --;

Line 58, "strage" should read -- stage --; and

Line 59, "process" should read -- processes --.

COLUMN 11:

Line 30, "whihe" should read -- which --; and

Line 31, "which" should read -- which the --.

COLUMN 12:

Line 31, "acumulated" should read -- accumulated --;

Line 35, "inn" should read -- in --; and

Line 61, "tht" should read -- the --.

COLUMN 13:

Line 1, "in" should read -- in an --;

Line 38, "ID"" should read -- ID" field --; and

Line 56, "e-mail" should read -- e-mail, --.

COLUMN 14:

Line 35, "numbers" should read -- numbers the --; and

Line 38, "chart" should read -- chart of --;

COLUMN 15:

Line 47, "same also" should read -- also the same --;

Line 61, "request" should read --requests --; and

Line 63, "retriving," should read -- retrieving, --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 2 9 2887

PATENT NO. <u>7,154,616 B2</u>



CERTIFICATE OF CORRECTION

PATENT NO. : 7,154,616 B2

DATED

: December 26, 2006

INVENTOR(S): Watanabe, et al.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16:

Line 1, "request" should read -- requests --;

Line 13, "request" should read -- requests --; and

Line 57, "at" should read -- At --.

COLUMN 18:

Line 4, "sheet" should read -- sheet, --.

COLUMN 19:

Line 2, "or outside server and "outside domain" should read -- or "outside server and outside domain" --;

Line 40, "thereof" should read -- thereof, --; and

Line 66, "necessarily" should read -- necessarily be --.

COLUMN 20:

Line 2, "as" should read -- as a --.

COLUMN 21:

Line 4, "anc" should read -- and --; and

Line 40, "in" should read -- in a --.

COLUMN 22:

Line 56, "in" should read -- in an --; and

Line 58, "shows" should read -- show --.

COLUMN 23:

Line 65, "contentration" should read -- concentration --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 2 3 2007

PATENT NO. 7,154,616 B2



CERTIFICATE OF CORRECTION

PATENT NO.

: 7,154,616 B2

DATED

: December 26, 2006

INVENTOR(S) : Watanabe, et al.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24:

Line 28, "numbers" should read -- numbers the --; and

Line 37, "in" (second occurrence) should be deleted.

COLUMN 25:

Line 17, "the" (first occurrence) should be deleted;

Line 27, "occupany" should read -- occupancy --;

Line 31, "is" should read -- is the --;

Line 57, "recording the" should read -- the recording--; and

Line 67, "i" should read -- in --.

COLUMN 26:

Line 3, "application" should read -- application --.

COLUMN 27:

Line 21, "normal" should read -- "normal --.

COLUMN 28:

Line 1, "numbers" should read -- numbers the --;

Line 5, "be" should read -- be the --;

Line 8, "request" should read -- requests --;

Line 12, "authentification" should read --authentication --:

Line 13, "authentification," should read -- authentication, --;

Line 22, "authentification" should read -- authentication --;

Line 37, "are" should read -- are the --; and

Line 37, "numbers" should read -- numbers the --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 2 9 2007

PATENT NO. 7,154,616 B2

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) 1573071v1(Form#30)

CERTIFICATE OF CORRECTION

PATENT NO. : 7,154,616 B2

DATED: December 26, 2006

INVENTOR(S): Watanabe, et al.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 29:

Line 8, "providere" should read -- provider --;

Line 26, "also" should read -- also be --; and

Line 44, "printing" (second occurrence) should read -- printing", --.

COLUMN 30:

Line 6, "are" should read -- are the --;

Line 6, "numbers" should read -- numbers the --; and

Line 57, "[Nineth" should read -- [Ninth --.

COLUMN 31:

Line 19, "sheetg" should read -- sheet --;

Line 28, "8 for" should read -- (for --;

Line 47, "are" should read -- are the --; and

Line 48, "numbers" should read -- numbers the --.

COLUMN 33:

Line 15, "art" should read -- an --; and

Line 24, "a" should read -- an --.

FCHS_WS 1573071v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 29 7997

PATENT NO. <u>7,154,616 B2</u>



CERTIFICATE OF CORRECTION

PATENT NO. : 7,154,616 B2

DATED: December 26, 2006

INVENTOR(S) : Watanabe, et al.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS:

SHEET 10:

FIG. 11, in block 33, "PRINT DRIVVER" should read -- PRINT DRIVER --.

COLUMN 2:

Line 62, "ve" should read -- be --.

COLUMN 5:

Line 8, "shape" should read -- shape, --;

Line 9, "etc." should read -- etc., --;

Line 28, "applicational," should read -- application --;

Line 40, "standalone" should read -- stand-alone --; and

Line 53, "in" should read -- in the --.

COLUMN 7:

Line 7, "sheets" should read -- sheets, --; and

Line 10, "erared" should read -- erased --.

COLUMN 8:

Line 24, "apparatus" should read -- apparatus, --; and

Line 44, "MFP 3" should read -- MFP 3, --.

COLUMN 9:

Line 26, "where by" should read -- whereby --; and

Line 51, "listg" should read -- list --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) 1573071v1(Form#30)

PATENT NO. 7,154,616 B2

No. of add'l. copies @ 30¢ per page

NOV 29 2007

CERTIFICATE OF CORRECTION

PATENT NO.

: 7,154,616 B2

DATED

: December 26, 2006

INVENTOR(S) : Watanabe, et al.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 48, "process" should read -- processes --;

Line 58, "strage" should read -- stage --; and

Line 59, "process" should read -- processes --.

COLUMN 11:

Line 30, "whihe" should read -- which --; and

Line 31, "which" should read -- which the --.

COLUMN 12:

Line 31, "acumulated" should read -- accumulated --;

Line 35, "inn" should read -- in --; and

Line 61, "tht" should read -- the --.

COLUMN 13:

Line 1, "in" should read -- in an --;

Line 38, "ID" should read -- ID" field --; and

Line 56, "e-mail" should read -- e-mail, --.

COLUMN 14:

Line 35, "numbers" should read -- numbers the --; and

Line 38, "chart" should read -- chart of --;

COLUMN 15:

Line 47, "same also" should read -- also the same --;

Line 61, "request" should read --requests --; and

Line 63, "retriving," should read -- retrieving, --.

FITZPATRICK, CELLA, HARPER & SCINTO

MAILING ADDRESS OF SENDER:

PATENT NO. <u>7,154,616 B2</u>

No. of add'l. copies @ 30¢ per page

30 Rockefeller Plaza New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 2 9 2907

CERTIFICATE OF CORRECTION

PATENT NO. : 7,154,616 B2

DATED: December 26, 2006

INVENTOR(S): Watanabe, et al.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16:

Line 1, "request" should read -- requests --;

Line 13, "request" should read -- requests --; and

Line 57, "at" should read -- At --.

COLUMN 18:

Line 4, "sheet" should read -- sheet, --.

COLUMN 19:

Line 2, "or outside server and "outside domain" should read -- or "outside server and outside domain" --;

Line 40, "thereof" should read -- thereof, --; and

Line 66, "necessarily" should read -- necessarily be --.

COLUMN 20:

Line 2, "as" should read -- as a --.

COLUMN 21:

Line 4, "anc" should read -- and --; and

Line 40, "in" should read -- in a --.

COLUMN 22:

Line 56, "in" should read -- in an --; and

Line 58, "shows" should read -- show --.

COLUMN 23:

Line 65, "contentration" should read -- concentration --.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>7,154,616 B2</u>

No. of add'l. copies @ 30¢ per page

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 29 2007

CERTIFICATE OF CORRECTION

PATENT NO. : 7,154,616 B2

DATED: December 26, 2006

INVENTOR(S) : Watanabe, et al.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24:

Line 28, "numbers" should read -- numbers the --; and

Line 37, "in" (second occurrence) should be deleted.

COLUMN 25:

Line 17, "the" (first occurrence) should be deleted;

Line 27, "occupany" should read -- occupancy --;

Line 31, "is" should read -- is the --;

Line 57, "recording the" should read -- the recording--; and

Line 67, "i" should read -- in --.

COLUMN 26:

Line 3, "application" should read -- application --.

COLUMN 27:

Line 21, "normal" should read -- "normal --.

COLUMN 28:

Line 1, "numbers" should read -- numbers the --;

Line 5, "be" should read -- be the --;

Line 8, "request" should read -- requests --;

Line 12, "authentification" should read --authentication --;

Line 13, "authentification," should read -- authentication, --:

Line 22, "authentification" should read -- authentication --;

Line 37, "are" should read -- are the --; and

Line 37, "numbers" should read -- numbers the --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

NOV 2 9 2007

PATENT NO. 7,154,616 B2



CERTIFICATE OF CORRECTION

PATENT NO. : 7,154,616 B2

DATED : December 26, 2006

INVENTOR(S): Watanabe, et al.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 29:

Line 8, "providere" should read -- provider --;

Line 26, "also" should read -- also be --; and

Line 44, "printing" (second occurrence) should read -- printing", --.

COLUMN 30:

Line 6, "are" should read -- are the --;

Line 6, "numbers" should read -- numbers the --; and

Line 57, "[Nineth" should read -- [Ninth --.

COLUMN 31:

Line 19, "sheetg" should read -- sheet --;

Line 28, "8 for" should read -- (for --;

Line 47, "are" should read -- are the --; and

Line 48, "numbers" should read -- numbers the --.

COLUMN 33:

Line 15, "art" should read -- an --; and

Line 24, "a" should read -- an --.

FCHS_WS 1573071v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 7,154,616 B2

No. of add'l. copies @ 30¢ per page

NOV 29 2007

